

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
Telephone: 856-858-4800 Fax: 856-786-5974
EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
Environmental Design, Inc. [EDI50]
5434 King Avenue, Suite 101
Pennsauken, NJ 08109
(856) 616-9516
tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
Newark, NJ (7 Schools) / Project #:
Customer PO: BR-230603-0960
EMSL Sales Rep: Sheryl Stearnes
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Analytical Results

Analyte	Result	Q	DF	RL	Units	Prepared Date/Time	Analyzed Date/Time	Analyst Initials	Prep /Analytical Method
Sample: 87-B-01-DW / Kitchen Left Sink Lims Reference ID: AB57605-01 Matrix: Drinking Water Sampled: 06/21/23 06:05:00									
Metals									
Copper	36		1	35	µg/L	06/22/23 12:19	06/22/23 17:52	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 17:52	JW1	EPA 200.8
Sample: 87-B-02-DW / Kitchen Right Sink Lims Reference ID: AB57605-02 Matrix: Drinking Water Sampled: 06/21/23 06:05:00									
Metals									
Copper	38		1	35	µg/L	06/22/23 12:19	06/22/23 18:09	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:09	JW1	EPA 200.8
Sample: 87-B-03-ND / Men's Restroom Sink Lims Reference ID: AB57605-03 Matrix: Drinking Water Sampled: 06/21/23 06:07:00									
Metals									
Copper	72		1	35	µg/L	06/22/23 12:19	06/22/23 18:11	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:11	JW1	EPA 200.8
Sample: 87-B-04-ND / Women's Restroom Sink Lims Reference ID: AB57605-04 Matrix: Drinking Water Sampled: 06/21/23 06:08:00									
Metals									
Copper	97		1	35	µg/L	06/22/23 12:19	06/22/23 18:14	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:14	JW1	EPA 200.8
Sample: 87-B-05-ND / Women's Restroom Sink Near F Lims Reference ID: AB57605-05 Matrix: Drinking Water Sampled: 06/21/23 06:09:00									
Metals									
Copper	35		1	35	µg/L	06/22/23 12:19	06/22/23 18:16	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:16	JW1	EPA 200.8
Sample: 87-B-06-ND / Men's Restroom Sink Near Fire Lims Reference ID: AB57605-06 Matrix: Drinking Water Sampled: 06/21/23 06:09:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 18:23	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:23	JW1	EPA 200.8
Sample: 87-B-07-DW / Water Cooler in Lunchroom Lims Reference ID: AB57605-07 Matrix: Drinking Water Sampled: 06/21/23 06:10:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 18:25	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:25	JW1	EPA 200.8
Sample: 87-1-08-DW / Water Cooler in Room 2 Lims Reference ID: AB57605-08 Matrix: Drinking Water Sampled: 06/21/23 06:16:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 18:28	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:28	JW1	EPA 200.8

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
Telephone: 856-858-4800 Fax: 856-786-5974
EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
Environmental Design, Inc. [EDI50]
5434 King Avenue, Suite 101
Pennsauken, NJ 08109
(856) 616-9516
tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
Newark, NJ (7 Schools) / Project #:
Customer PO: BR-230602-0960
EMSL Sales Rep: Sheryl Steinhilber
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Analytical Results (Continued)

Analyte	Result	Q	DF	RL	Units	Prepared Date/Time	Analyzed Date/Time	Analyst Initials	Prep /Analytical Method
---------	--------	---	----	----	-------	-----------------------	-----------------------	---------------------	----------------------------

Sample: 87-1-08-DW / Water Cooler in Room 2 (Conti) Lims Reference ID: AB57605-08 Matrix: Drinking Water Sampled: 06/21/23 06:16:00

Metals (Continued)

Sample: 87-1-09-ND / Room 2 Sink Lims Reference ID: AB57605-09 Matrix: Drinking Water Sampled: 06/21/23 06:18:00

Metals

Copper	46	1	35	µg/L	06/22/23 12:19	06/22/23 18:30	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:30	JW1	EPA 200.8

Sample: 87-1-10-ND / Restroom Outside Supervisor's Lims Reference ID: AB57605-10 Matrix: Drinking Water Sampled: 06/21/23 06:21:00

Metals

Copper	62	1	35	µg/L	06/22/23 12:19	06/22/23 18:33	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:33	JW1	EPA 200.8

Sample: 87-1-11-ND / Ladies Restroom Left Sink (Nea Lims Reference ID: AB57605-11 Matrix: Drinking Water Sampled: 06/21/23 06:23:00

Metals

Copper	<35	1	35	µg/L	06/22/23 12:19	06/22/23 18:35	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:35	JW1	EPA 200.8

Sample: 87-1-12-ND / Ladies Restroom Middle Sink (N Lims Reference ID: AB57605-12 Matrix: Drinking Water Sampled: 06/21/23 06:23:00

Metals

Copper	57	1	35	µg/L	06/22/23 12:19	06/22/23 18:42	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:42	JW1	EPA 200.8

Sample: 87-1-13-ND / Men's Restroom Left Sink (Outs Lims Reference ID: AB57605-13 Matrix: Drinking Water Sampled: 06/21/23 06:25:00

Metals

Copper	<35	1	35	µg/L	06/22/23 12:19	06/22/23 18:44	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:44	JW1	EPA 200.8

Sample: 87-1-14-ND / Men's Restroom Middle Sink (O Lims Reference ID: AB57605-14 Matrix: Drinking Water Sampled: 06/21/23 06:25:00

Metals

Copper	<35	1	35	µg/L	06/22/23 12:19	06/22/23 18:51	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:51	JW1	EPA 200.8

Sample: 87-1-15-ND / Unisex Restroom Sink (Near Rm Lims Reference ID: AB57605-15 Matrix: Drinking Water Sampled: 06/21/23 06:27:00

Metals

Copper	44	1	35	µg/L	06/22/23 12:19	06/22/23 18:54	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 12:19	06/22/23 18:54	JW1	EPA 200.8

Sample: 87-1-16-ND / Unisex Restroom Sink (Near Rm Lims Reference ID: AB57605-16 Matrix: Drinking Water Sampled: 06/21/23 06:27:00

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
 Telephone: 856-858-4800 Fax: 856-786-5974
 EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
 Environmental Design, Inc. [EDI50]
 5434 King Avenue, Suite 101
 Pennsauken, NJ 08109
 (856) 616-9516
 tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
 Newark, NJ (7 Schools) / Project #:
Customer PO: PR-230603-0960
EMSL Sales Rep: Sheryl Steinfeld
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Analytical Results

(Continued)

Analyte	Result	Q	DF	RL	Units	Prepared Date/Time	Analyzed Date/Time	Analyst Initials	Prep /Analytical Method
Sample: 87-1-16-ND / Unisex Restroom Sink (Near Rm Lims Reference ID: AB57605-16 Matrix: Drinking Water Sampled: 06/21/23 06:27:00									
Metals									
Copper	47		1	35	µg/L	06/22/23 12:19	06/22/23 18:56	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:56	JW1	EPA 200.8
Sample: 87-2-17-DW / Kitchen Sink Lims Reference ID: AB57605-17 Matrix: Drinking Water Sampled: 06/21/23 06:31:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 18:59	JW1	EPA 200.8
Lead	3.67		1	1.00	µg/L	06/22/23 12:19	06/22/23 18:59	JW1	EPA 200.8
Sample: 87-2-18-ND / Teacher's Restroom Sink Lims Reference ID: AB57605-18 Matrix: Drinking Water Sampled: 06/21/23 06:32:00									
Metals									
Copper	42		1	35	µg/L	06/23/23 14:44	06/27/23 18:36	JW1	EPA 200.8
Lead	5.83		1	1.00	µg/L	06/23/23 14:44	06/27/23 18:36	JW1	EPA 200.8
Sample: 87-2-19-DW / Water Cooler in Room 1 Lims Reference ID: AB57605-19 Matrix: Drinking Water Sampled: 06/21/23 06:34:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 19:01	JW1	EPA 200.8
Lead	<1.00		1	1.00	µg/L	06/22/23 12:19	06/22/23 19:01	JW1	EPA 200.8
Sample: 87-2-20-ND / Room 1 Sink Lims Reference ID: AB57605-20 Matrix: Drinking Water Sampled: 06/21/23 06:36:00									
Metals									
Copper	<35		1	35	µg/L	06/22/23 12:19	06/22/23 19:03	JW1	EPA 200.8
Lead	7.23		1	1.00	µg/L	06/22/23 12:19	06/22/23 19:03	JW1	EPA 200.8
Sample: 87-2-21-ND / Girl's Restroom Sink (Right Side) Lims Reference ID: AB57605-21 Matrix: Drinking Water Sampled: 06/21/23 06:36:00									
Metals									
Copper	91		1	35	µg/L	06/22/23 12:19	06/22/23 19:06	JW1	EPA 200.8
Lead	18.0		1	1.00	µg/L	06/22/23 12:19	06/22/23 19:06	JW1	EPA 200.8
Sample: 87-2-22-ND / Boy's Restroom Sink (Left Side) Lims Reference ID: AB57605-22 Matrix: Drinking Water Sampled: 06/21/23 06:36:00									
Metals									
Copper	56		1	35	µg/L	06/23/23 14:44	06/27/23 18:39	JW1	EPA 200.8
Lead	8.14		1	1.00	µg/L	06/23/23 14:44	06/27/23 18:39	JW1	EPA 200.8
Sample: 87-2-23-ND / Room 10 Sink Lims Reference ID: AB57605-23 Matrix: Drinking Water Sampled: 06/21/23 06:38:00									
Metals									
Copper	90		1	35	µg/L	06/22/23 13:50	06/22/23 21:02	JW1	EPA 200.8
Lead	18.7		1	1.00	µg/L	06/22/23 13:50	06/22/23 21:02	JW1	EPA 200.8

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
Telephone: 856-858-4800 Fax: 856-786-5974
EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
Environmental Design, Inc. [EDI50]
5434 King Avenue, Suite 101
Pennsauken, NJ 08109
(856) 616-9516
tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
Newark, NJ (7 Schools) / Project #:
Customer PO: PR-230602-0960
EMSL Sales Rep: Sherry Stearns
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Analytical Results

(Continued)

Analyte	Result	Q	DF	RL	Units	Prepared Date/Time	Analyzed Date/Time	Analyst Initials	Prep /Analytical Method
---------	--------	---	----	----	-------	-----------------------	-----------------------	---------------------	----------------------------

Sample: 87-2-23-ND / Room 10 Sink (Continued)**Lims Reference ID:** AB57605-23 **Matrix:** Drinking Water**Sampled:** 06/21/23 06:38:00**Metals (Continued)****Sample:** 87-BLANK-24 / DI Blank**Lims Reference ID:** AB57605-24 **Matrix:** Drinking Water**Sampled:** 06/21/23 00:00:00**Metals**

Copper	<35	1	35	µg/L	06/22/23 13:50	06/22/23 21:05	JW1	EPA 200.8
Lead	<1.00	1	1.00	µg/L	06/22/23 13:50	06/22/23 21:05	JW1	EPA 200.8

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
Telephone: 856-858-4800 Fax: 856-786-5974
EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
Environmental Design, Inc. [EDI50]
5434 King Avenue, Suite 101
Pennsauken, NJ 08109
(856) 616-9516
tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
Newark, NJ (7 Schools) / Project #:
Customer PO: BR-230602-0960
EMSL Sales Rep: Sheryl Steinhilber
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Certified Analyses included in this Report

Analyte	CAS #	Certifications
EPA 200.8 in Drinking Water		
Copper	7440-50-8	NJDEP
Lead	7439-92-1	NJDEP

List of Certifications

Code	Description	Number	Expires
MADEP	Massachusetts Department of Environmental Protection	M-NJ337	06/30/2023
California ELAP	California Water Boards	1877	06/30/2024
A2LA	A2LA Environmental Certificate	2845.01	07/31/2024
AIHA LAP	EMSL Analytical, Inc. Cinnaminson, NJ AIHA-LAP, LLC-ELLAP Accredited	100194	01/01/2025
NJDEP	New Jersey Department of Environmental Protection	03036	06/30/2023
PADEP	Pennsylvania Department of Environmental Protection	68-00367	11/30/2023
NYSDOH	New York State Department of Health	10872	04/01/2024
CTDPH	Connecticut Department of Public Health	PH-0270	06/23/2023

Please see the specific Field of Testing (FOT) on www.emsl.com <<http://www.emsl.com>> for a complete listing of parameters for which EMSL is certified.

**EMSL Analytical, Inc.**

200 Route 130, Cinnaminson, NJ, 08077
Telephone: 856-858-4800 Fax:856-786-5974
EMSL-CIN-01

EMSL Order ID: 012357605**LIMS Reference ID:** AB57605**EMSL Customer ID:** EDI50

Attention: Tom Pruno
Environmental Design, Inc. [EDI50]
5434 King Avenue, Suite 101
Pennsauken, NJ 08109
(856) 616-9516
tp@editesting.com

Project Name: La Casa de Don Pedro - 87 St. Francis,
Newark, NJ (7 Schools) / Project #:
Customer PO: ~~PR-230602-0960~~
EMSL Sales Rep: Sheryl Steinmetz
Received: 06/21/2023 13:30
Reported: 06/28/2023 16:33

Notes and Definitions

Item	Definition
D	Analyte was reported from a dilution run.
[2C]	Reported from the second channel in dual column analysis.
DF	Dilution Factor
MDL	Method Detection Limit.
ND	Analyte was NOT DETECTED at or above the detection limit.
Q	Qualifier
RL	Reporting Limit

Measurement of uncertainty and any applicable definitions of method modifications are available upon request. Per EPA NLLAP policy, sample results are not blank corrected.

Owen McKenna Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted."

Environmental Design Inc.

Professional Environmental Consultants



Lead (Pb) and Copper in Water Sampling Chain of Custody

EMSL Order ID (Lab Use Only): 4857605

Company:	Environmental Design Inc. (EDI-50)	EMSL Bill To:	EDI-50
Street:	5434 King Avenue, Suite 101	Phone:	856-616-9516
City/State/Zip:	Pennsauken, NJ 08109	Fax:	856-616-9519
Send Report To:	Tom Pruno	Send Results To:	tp@editesting.com
State Samples Taken:	NJ	Turnaround Time (TAT):	5 days

Matrix	Method	Instrument	Reporting Limit	Preservative
EPA Lead & Copper Rule Drinking & Other water	EPA 200.8	Test for lead and copper	0.001 mg/L (ppm)	Nitric acid (HNO ₃)

EDI Client/Site: La Casa de Don Pedro - 87 St Francis, Newark, NJ (7 schools) EDI Project #: PR-230602-0960

Special Instructions PLEASE PROVIDE STANDARD REPORT AS WELL AS AN EXCEL DATA FILE. TEST FOR 2 ANALYTES, LEAD & COPPER.

Sample #	Sample Description/Location	Volume	Date/Time Sampled
1 87-B-01 DW	Kitchen Left Sink	250 mL	6/21/2023 6:05 am 73.4 °F / 54.5 %RH
2 87-B-02-DW	Kitchen Right Sink	250 mL	6/21/2023 6:05 am 73.4 °F / 54.5 %RH
3 87-B-03-ND	Men's Restroom Sink	250 mL	6/21/2023 6:07 am 72.6 °F / 56.9 %RH
4 87-B-04-ND	Women's Restroom Sink	250 mL	6/21/2023 6:08 am 72.6 °F / 56.9 %RH
5 87-B-05-ND	Women's Restroom Sink near Fire Exit	250 mL	6/21/2023 6:09 am 72.3 °F / 57.8 %RH
6 87-B-06-ND	Men's Restroom Sink near Fire Exit	250 mL	6/21/2023 6:09 am 72.3 °F / 57.8 %RH
7 87-B-07 DW	Water Cooler in Lunchroom	250 mL	6/21/2023 6:10 am 72.3 °F / 57.8 %RH
8 87-1-08-DW	Water Cooler in Room 2	250 mL	6/21/2023 6:16 am 73.2 °F / 55.6 %RH
9 87-1-09-ND	Room 2 Sink	250 mL	6/21/2023 6:18 am 72.3 °F / 57.8 %RH
10 87-1-10-ND	Restroom Outside Supervisor's Office	250 mL	6/21/2023 6:21 am 71.6 °F / 55.8 %RH
11 87-1-11-ND	Ladies Restroom Left Sink (Near Indoor Playground)	250 mL	6/21/2023 6:23 am 70.9 °F / 56.7 %RH
12 87-1-12-ND	Ladies Restroom Middle Sink (Near Indoor Playground)	250 mL	6/21/2023 6:23 am 70.9 °F / 56.7 %RH
13 87-1-13-ND	Men's Restroom Left Sink (Outside Rm 5 & 6)	250 mL	6/21/2023 6:25 am 70.9 °F / 56.7 %RH
14 87-1-14-ND	Men's Restroom Middle Sink (Outside Rm 5 & 6)	250 mL	6/21/2023 6:25 am 70.9 °F / 56.7 %RH
15 87-1-15-ND	Unisex Restroom Sink (Near Rm 5 - Closest to door)	250 mL	6/21/2023 6:27 am 70.9 °F / 56.7 %RH
16 87-1-16-ND	Unisex Restroom Sink (Near Rm 6 - Closest to door)	250 mL	6/21/2023 6:27 am 70.9 °F / 56.7 %RH

Relinquished:	S. Acevedo	Received By:	S. Acevedo
Date:	6-21-23	Date:	6/21/23
Sampler(s):	S. Acevedo	Total Samples:	24
		Page:	1 of 2

EDI is a Service Disabled Veteran Owned Small Business!

Re-purchased
Blank - 40000
6/21/23 13:35 EL



Elkay 6/21/23 13:30

Environmental Design Inc.

Professional Environmental Consultants



Lead (Pb) and Copper in Water Sampling Chain of Custody

EMSL Order ID (Lab Use Only):

AD 57605

Company:	Environmental Design Inc. (EDI-50)	EMSL Bill To:	EDI-50
Street:	5434 King Avenue, Suite 101	Phone:	856-616-9516
City/State/Zip:	Pennsauken, NJ 08109	Fax:	856-616-9519
Send Report To:	Tom Pruno	Send Results To:	tp@editesting.com
State Samples Taken:	NJ	Turnaround Time (TAT):	5 days

Matrix	Method	Instrument	Reporting Limit	Preservative
EPA Lead & Copper Rule Drinking & Other water	EPA 200.8	Test for lead and copper	0.001 mg/L (ppm)	Nitric acid (HNO ₃)

EDI/Client/Site: La Casa de Don Pedro - 87 St Francis, Newark, NJ (7 schools)

EDI/Project #: PR-230602-0960

Special Instructions PLEASE PROVIDE STANDARD REPORT AS WELL AS AN EXCEL DATA FILE. TEST FOR 2 ANALYTES, LEAD & COPPER.

Sample #	Sample Description/Location	Volume	Date/Time Sampled
17 87-2-17-DW	Kitchen Sink	250 mL	6/21/2023 6:31 am 72.1 °F / 48.4 %RH
18 87-2-18-ND	Teacher's Restroom Sink	250 mL	6/21/2023 6:32 am 73.4 °F / 46.6 %RH
19 87-2-19-DW	Water Cooler in Room 1	250 mL	6/21/2023 6:34 am 71.5 °F / 48.0 %RH
20 87-2-20-ND	Room 1 Sink	250 mL	6/21/2023 6:36 am 71.5 °F / 48.0 %RH
21 87-2-21-ND	Girl's Restroom Sink (Right Side)	250 mL	6/21/2023 6:36 am 69.5 °F / 46.6 %RH
22 87-2-22-ND	Boy's Restroom Sink (Left Side)	250 mL	6/21/2023 6:36 am 69.5 °F / 46.6 %RH
23 87-2-23-ND	Room 10 Sink	250 mL	6/21/2023 6:38 am 71.5 °F / 48.0 %RH
24 87-BLANK-24	DI Blank	250 mL	6/21/2023 N/A 65.8 °F / 59.8 %RH Outside Control

Relinquished:	S. Acevedo	Received By:	
Date:	6-21-23	Time:	
Sampler(s):	S. Acevedo	Total Samples:	24
		Page:	2 of 2

EDI is a Service Disabled Veteran Owned Small Business!

